

Resurvey of a Portion of the Subdivisions of
T.28 S., R.61 E.

chains

- 11.00 Left bank of a wash, course NW.; ascend 50 ft. to
19.00 Right bank of wash, course NW.; ascend 260 ft. over a
broken SW. slope.
38.73 The cor. of secs. 29, 30, 31, and 32.

Land, rolling and mountainous.
Soil, gravelly, 3d rate; and rocky, 4th rate.
Undergrowth, creosote brush, sage and cacti.

There is no final test of the solar attachment to be recorded as the solar attachment was used to determine the course only at the beginning of the survey. All lines surveyed were checked against each other or against the California-Nevada State Boundary line, by deflection.

GENERAL DESCRIPTION

The land in sec. 31, T.28 S., R.61 E. is rolling hills and rough mountainous in character. A dividing ridge bears about N.60°E. and S.60°W. thru the center of the section, from which many small spurs and ravines shoot off to the NW. or SW.

The soil is gravelly, 3d rate and rocky, 4th rate. There is little indication of mineral bearing rock in the section, altho there are some prospect location mounds scattered about.

There is no water in this section; and no timber; the undergrowth is scattering and consists of creosote brush, cacti and sage brush.
