

20

24

Resurvey of a Portion of the California-Nevada
State Boundary.

Chains.	Land, level and rolling. Soil, sandy, 2nd rate; and gravelly; 3rd rate. Timber, none. Undergrowth, scattered cactus and sage.
	S.45°40'E., on tangent and true line. Over rolling land, through scattered undergrowth.
12.80	Old road, bears NE. and SW.
12.90	Foot of hills, bears NE. and SW.; asc. 84 ft. over NW. slope.
22.80	Top of ascent; desc. 69 ft.
26.00	Drain, course SW.; asc. 29 ft.
32.70	Spur, slopes S.; desc. 17 ft. over SE. slope.
38.50	Wash, 35 lks. wide, course SW.
40.00	Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $5\frac{1}{2}$ mile cor. with brass cap mkd.
	<div style="text-align: center;"> 134 CAL X NEV 5$\frac{1}{2}$ M 1933 </div>
	raise a mound of stone, 3 ft. base, 2 ft. high, SW. of cor.
41.40	Wash, 20 lks. wide, course SW.; asc. 91 ft. over SW. slope.
50.00	Top of ascent; desc. 51 ft.
62.10	Wash, 15 lks. wide, course SW.; asc. 127 ft. over NW. slope.
70.85	Monument 135 on California-Nevada State line, which is a redwood post, 4 ins. sq., 1 ft. exposed, set in a mound of stone, 4 $\frac{1}{2}$ ft. base, 2 ft. high, marked 135 on NW., N on NE. and C on SW. sides; on top of hill bears NE. and SW.
	Land, rolling. Soil, gravelly, 3 rd rate; and rocky, 4th rate. Timber, none. Undergrowth, scattered creosote brush, cactus and sage.
	Monument 136 was not established in the Coast and Geodetic Survey of the California-Nevada State Boundary. The flag at Monument 137 being visible, I run
	S.45°39'E., on tangent and true line. Over rolling desert hills, through scattered desert growth. Descend 127 ft. over SE. slope.
17.00	Foot of hill, bears NE. and SW.; continue over level land.
40.00	Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{2}$ mile cor., with brass cap mkd.