## Resurvey of the Ideho-Nevada State Boundary Line from the 100 to the 120 Mile Post.

Chaina

196.16 Irrigation ditch, course N.

224.16 Irrigation ditch, course N. 45° V.

227.55 Barbed wire fence, brs. F. 15° E. and S. 15° W.

242.16 The 109 mile post.

hand, nearly level, agricultural, 242.16 chs. Soil, gravelly loam, 2nd rate.
No timber.

June 27, 1911.

June 28, 1911. At 8.00 a.m., l.m.t., I set off 42° 00'N. on the lat. arc, and 23° 20' N. on the decl. arc, and determine a meridian with the solar, at the 112th mile post on the Idaho-Nevada state boundary line.

Thence I run

West on a random line along the 113th mile.

80.79 Falls 5 lks. N. of the 115th mile post which is a mound of earth as witnessed and described in original notes.

Thence I run

N. 89° 58' E. on a true line along the 112th mile. Over rolling, sage-brush flat.

16.25 Falls 4 lks. S. of a mound containing a stake, - no marks distinguishable.

40.55 Dry drain, course N.

80.79 The 112th mile post.

Land, gently rolling. - agricultural, 80.79 chs. Soil, gravelly, 2nd rate. No timber.

June 28, 1911. At this post, I set off 23° 19° N. on the decl. arc, and at 12h O3m p.m., l.m.t., observe the sun on the meridian; the resulting lat. is 42° 00°.

From the 113 mile post, I run

West on a random line along the 114th mile.

80.83 Falls 9 lks. 8. of the 114th mile post, on the IdahoNevada state boundary line, which is a stone 24x12x4

ins., marked and witnessed as described by the original notes.