

Resurvey Moapa River Indian Reservation.

Chains	
	East on a random line bet. secs. 23 and 26.
40.55	Fall 7 lks. N. of a wooden post 4 ins. square, 3 ft. above ground, painted white and marked $\frac{1}{4}$ S 23 on N and S 26 on S. This post has probably been set by some local surveyor.
	Find no trace of old cor.
81.32	Fall 14 lks. N. of cor. of secs. 23, 24, 25 and 26, hereinbefore described.
	Thence I run
	N. 89° 54' W. on a true line bet. secs. 23 and 26,
	Over broken land.
10.00	Road brs. N. and S.
	Enter level bottom land, brs. N. and S.
14.10	Flat drain, course S.
34.60	Road brs. N. 20° W. and S. 20° E.
37.50	Drain, course S. 15° E.
40.77	The wooden post as described on random line.
50.60	Left bank of Moapa River, 20 lks. wide, course S. 15° W.
52.00	Leave level bottom, brs. N. and S.
	begin ascent of broken E. slope.
56.50	Top of bluff, brs. N. and S.
66.60	Draw, drains S. 45° E.
80.67	Top of ridge, brs. N. and S.
81.32	The cor. of secs. 22, 23, 26 and 27.
	Land, level and broken.
	Soil, sandy loam, 1st rate; and stony, 3rd rate.

September 26, 1912, at the cor. of secs. 1, 6, 7 and 12, bet. Rgs. 65 and 66 E., T. 15 S., I set off 1st 19' S. on the declination arc, and at 11h. 51m. 13s., a.m., 1.m.t., observe the sun on the meridian; the resulting latitude is 36° 40', the proper latitude.

Thence I run

South on a random line bet. secs. 7 and 12.