

172

181

T 5 N. R 27 E

ground, marked  $\frac{1}{4}$  for  $\frac{1}{4}$  Sec. cor. Where  
Pine 19<sup>in</sup> di; bears N 24° E, 60<sup>in</sup> dist

Pine 14<sup>in</sup> di. bears N 36° W 34<sup>in</sup> dist

79.30 Rough Creek 40<sup>in</sup> wide N 85° E, ascend

81.70 Intersect the 1<sup>st</sup> Standard Parallel

North at a point 18<sup>ch</sup> 98<sup>in</sup> West of  
the Standard Cor to Secs. 32<sup>nd</sup> and 33 of  
T 6, N. R 27 E. Where I set a  
cleared post 4 $\frac{1}{2}$  long 4x4 in, 12<sup>in</sup> in  
ground, in ground  $\frac{1}{2}$  high, with pile  
24x18x12 in, marked for closing Cor  
to Secs. 4<sup>th</sup> and 5

Land Mountainous - Good Cattle  
Pine and Cedar timber

July 13<sup>th</sup> 1878

West Between Sections 5 and 8  
Var. 17° E,

6.00 Creek 10<sup>in</sup> wide E of N, ascend  
20.00 Leave timber  $\frac{1}{2}$  W and S E of W and E.  
30.00 Summit of ridge N W and E.

+