

S. B., T. 31 N., R. 61 E., Mt. D. M.

Chas. S. Preble Oct. 16th 1880.

Standard
From the Cor. to Tps.

31 N. Rs. 61 & 62 E.

I run,

North on a true line between sections 31-36.

Va. 17' 15' East.

Ascend.

40.00 Set Post 4 in. dia., 2 ft. in earth, 2 ft. above, for $\frac{1}{4}$ sec. cor.

from which bears a,

Pine 12 in. dia. N. 31° E. 12 lks. dist.

Cedar 8 in. dia. N. 16 $\frac{1}{2}$ ° W. 22 lks. dist.

80.00. Set Post, 4 in. square, 2 ft. in earth, 2 ft. above, for cor.

to secs. 31-31-25-36.

from which bears a,

Pine 14 in. dia. S. 26° E. 38 lks. dist.

Cedar 6 in. dia. N. 10° E. 16 lks. dist.

Cedar 9 in. dia. S. 25° W. 18 lks. dist.

Land slopes East.

Soil 2nd, & 2d. rate.

Timber and undergrowth of Pine, Cedar and
Sagebrush.