

16 286
8¹/₂ Standard line North along
212 S. B., T. 41 N., R. 69 E., Mt. D. M.

Standard
From the Cor. to Tps. 41 N. Rs. 68 & 69 E.
I run,

East on a true line on S. B. of Section 31
Va. $17^{\circ}30'$ East.

Descend.

40.00 Set Post 4 in. dia., 2 ft. in earth, 2 ft. above, for $\frac{1}{4}$ sec. cor.
from which bears a,

Cedar 10 in. dia. A. 63° E. 25 lks. dist.

Cedar 12 in. dia. A. 17° W. 30 lks. dist.

50.00 Leave Limber, leave Ar. S. and descend.

80.00 Set Post 4 in. square, 1 ft. in earth, 1 ft. above Earth mound,
 $4\frac{1}{2}$ ft. in diameter at base, by 2 ft. in height, and dug pits,
24 x 18 x 12, 8 lks. dist., at 4 angles, for cor. to secs.

31- 32.

Land mountainous.

Soil 3rd rate

Timber and undergrowth of Pmi. Cedar
Bunchgrass & Sagebrush.