

72

194

N. B., T. 4 N., R. 54 E., Mt. D. M.

North on a true line between sections 1-6.

Va. 17° East.

Ascend.

27.50 Cross Gulch, 10 lks. wide, Course S. E.

36.50 Cross Gulch, 15 lks. wide, Course S. 50° E.

40.50 Set Sand Stone 12 x 8 x 8, in Earth mound, 4 ft. in diameter at base, by 2 ft. in height, and dug pit 24 x 18 x 12, 8 lks East for $\frac{1}{4}$ sec. cor.

52.30 Cross Gulch, 10 lks. wide, Course S. 30° E.

60.50 Top of Spur, bears N. 50° E. & S. 50° W. and descend.

80.00 Set Sand Stone 10 x 8 x 6, in Earth mound, 4 ft. in diameter at base, by 2 ft. in height, and dug pits 24 x 18 x 12, 8 lks, dist., at 4 angles, for

The Cor. to Tps. 4 & 5 N. Rs. 53 & 54 E.

Land rolling.

Soil 2d. rate

Undergrowth of Sagebrush.

I carefully examined the adjustments of my solar compass to-day, particularly the latitude and reversing apparatus, and found them correct. July 16, 1888.

Before proceeding to subdivide this Tp., I made a change of 6 minutes in the latitude arc of my solar compass by adding same