

Exteriors T39N R65E MDM S. Bdy

Beginning on August 9th 1894
at the SE cor of T39N R64E.

which is a rock. 6" x 6" x 6 ins
above ground, ^{properly marked} with a rock mound
3^{ft} high 4 ft base alongside.

Run

E. on S bdy of Twp. S. bdy. S 31

Var 17° 30' E.

- 32.00 Ravine S.E
- 33.00 Road NW & SE
- 40.00 No corner and after diligent search
for same set temporary 1/4 sec. cor
- 52.00 Mound and trace of pits old post.
Lying on ground broken, properly
and plainly marked for cor to secs
31. 32. 5 & 6. 15 lks. N of line which I
rebuild as follows
- Set a post 4^{ft} long. 4 ins sq. with
marked stone 12 in the ground