

Resurvey

Exteriors T38N R67E MDM

East Boundary

Sept 13th

Having examined the E bdy of this Township and finding most of the corners obliterated I resurvey as follows.

From the cor. to Twp 37 & 38 N Rs 67 & 68 E, which is a post. 4 ins sq. properly and plainly marked with mound and pits agreeing with notes furnished me by the Surveyor General.

N. bet secs. 31 & 36

Va 17° 26' E

4.0.00

~~Time~~
A rock 16 × 14 × 6. marked 1/4 lying on ground. reset same. 10 ins in the ground and dug pits 18 × 18 × 12 ins N 15° of rock 5 1/2 ft dist and raised a mound of earth 2 ft high 3 1/2 ft base alongside.