

Resurvey 190

Exterior T39 N R68 E MDM

East Boundary

S1°29'W bet sec. 31 & 36

Ta 17°30'E.

36.00 Dry Channel. course NE

40.00 No corner and after diligent search for same set a post 3 ft long 3 ins sq with marked stone. 12 ins in the ground for $\frac{1}{4}$ sec cor marked 44 S on W face dug pits 18x18x12 ins N & S of post 5 ft dist and raised a mound of earth 1 1/2 ft high 3 1/2 ft base around post.

46.25 Cross old road course NE & SW.

80.00 Old corner a post plainly and properly marked for cor t. Trips 38 & 39 N R68 & 69 E. lying on old mound with traces of pits rebuild as follows