

## Sub-Division Tract. T. 35 N. R. 36 E.

Chairs 12 ins in ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  on N face, dug pits  $18 \times 18 \times 12$  ins. N & E of post  $5\frac{1}{2}$  ft. dish. raised mound of earth  $1\frac{1}{2}$  ft. high  $3\frac{1}{2}$  ft. base around post.

80.23 Intersect 7<sup>th</sup> Standard Parallel North, 500 chs. N of stand, cor. to sees. ~~31~~ 31 & 32 already described. Where I set post 4 ft long 4 ins sq. with marked stone 12 ins in ground for closing cor. to sees. 4 & 5.

Marked: -

T. 35 N. R. 36 E. C. C. on S

S 5 on E & S 6 on W faces, with 5 notches on E & 1 notch on W edges dug pits  $18 \times 18 \times 12$  ins in each sec.  $5\frac{1}{2}$  ft. dish. raised mound of earth 2 ft. high 4 ft. base around post.

Demar

Heavy Sage brush & <sup>grasswood</sup> Sand hills  
Soil 4<sup>th</sup> rate. Dec. 28<sup>th</sup> 1888

I test my instr. today & find it in good adjustment. Mag. Var  $17^{\circ} 45' E$