

Retracing

6th Standard parallel N. through R. 43E.

June 12<sup>th</sup> 1893

Beginning at the S.W. cor. of T. 31N. R. 44E. on standard line, already described. I run West on S. 1/4 Sec. 36 with Va. 16°30'E.

2000  
36.75  
4000

Road N. E. to Cattle Mountain  
Dry wash S.E.  
Set post 4 ft. long 4 ins square 12 ins in ground for standard 1/4 Sec. cor. marked S.C. 1/4 on N. face. Dug pits 2x2x2 ft. E. & W. 5 1/2 ft. dist. and raised a mound of earth 2 ft. high by 4 1/2 ft. base around post.

At this point I find traces of old mound with piece of the old post in it but the marked end has been broken off.

6600  
7300  
8000

Road N. E.  
Dry wash S.E.  
Set post 4 ft. long 4 ins square with marked stone 12 ins. in ground for standard cor. to Secs. 35 & 36 marked; S.C. T. 31. R. 43E on N. S. 36 on E. 30  
S. 35 on W. faces with 1 groove on E. and 5 grooves on W. faces, dug pits 2x2x2 ft. N. E. & W. of post 5 1/2 ft. distant and raised mound of earth 2 ft. high by 4 1/2 ft. base around post.  
At this point I find traces of old mound with piece of old post.

Land rolling. Soil 2nd rate. Sagebrush & greasewood