

¹² Retracing.

22

6th Standard parallel N. through R. 43 E.

West on S. bdy. Sec. 31.

Na. 17.30' E.

1100.

Road N. N. E.

1300

Top of bank. Descend abruptly.

1525

Dry wash. S. S. W.

1900

Willow Creek 500 yds. wide. S.

Cabin on Creek bears S 15 Chs.

2300

Top of west bank of creek bottom.

4000

Set rock 14 x 8 x 5 ins. 9 ins. in ground for Standard
1/4 Sec. Cor. marked S. C. 1/4 on N. face, dug pits
2 x 2 x 2 ft. 5 1/2 ft. distant and raised mound
of earth 2 ft. high 4 1/2 ft. base alongside.
At this point I find an old post in the ground.
no marks.

8000

Set rock 17 x 6 x 6 ins. 11 ins. in ground for Standard
Cor. to Twp. 31 N. R. 42 & 43 E. marked
S. C. with 6 grooves on N., E., and W. faces.
Dug pits 30 x 24 x 12 ins. crosswise on each
line N. 8 ft. and E. & W. 4 ft. from stone and
raised a mound of earth 2 1/2 ft. high by 5 ft.
base alongside.
At this point I find traces of old mound & pits

Land rolling. Soil 1st & 2nd rate
Sagebrush greasewood and willows.