

47.
Retracing

Chains - N. 13. Twp. 27 N R. 32 E M. 5. M

Survey commenced May 7th 1893
with wth H. ^{2/3} L. C. Guly Solar
Transit - ^{2/3} a Steel Chain
Instrument examined ^{2/3}
found to be correct -

Being unable to find any
old corners on the South-
West Boundary of this Township
for reliable starting point,
I go to the Cor. to Secs.
30, 31, 25 ^{2/3} 36 on West Boundary
which is a Willow Post, 4 ft. long,
1/2 ins. square, with small mound
of earth ^{2/3} base of pits -
I rebuild the same ^{2/3}
Set a Post 4 ft. long, 4 ins. square,
with marked stone 12 ins. in
the ground marked T. 27 N. S. 30
on N. E. R. 32 E. S. 31 on S. E.
R. 31 E. S. 36 on S. R. ^{2/3} S. 25 on
N. W. face, with 5 notches on N
^{2/3} notch on S. edge, reducing
the pits 18 x 18 x 12 ins. in each
Sec. 5 1/2 ft. dist - ^{2/3} rebuilt the