Retracing 6th Standard line North along

Chains- S. B. Twp. 28 N. R 32 E. Mt. D. M.

Survey commenced May 8th 1893
with a 5 ft. 9/10 L. E. Gurley
Solar Transit- 9/10 a Steel Chain
Instrument- was properly
examined 9/10 found to be
in perfect adjustment-

After diligent search I was
unable to find any reliable
corners on the North-
Boundary of Twp. 27 N.
R. 32 E. in which to close
my Subdivision lines, I
therefore go to the Standard
Cor to Twps 28 N. R.s 31, 9/10 32 E.
which is a Willow Post-
properly marked, with-
Mound of Earth- 9/10 Pit
partially destroyed I rebuild
the mound to 2½ ft. high, 4½ ft-
base 9/10 re dug the pits 24 × 18 × 12 ins.