

Coasters T. 33 N. R. 47 E. M. 20

Commencing at the 1/4-section corner
between Sections 19 + 24 T. 33 N. R. 46
+ 47 E which is a stone firmly set and
properly marked as described in the
field notes furnished by the surveyor
general, I run,
N. between sections 19 and 24.
Va. $17^{\circ}45' E.$

4000 —

4350 Road N.E. + S.W.

Leave flats + ascend.

8000

At this point I find small mound nearly
destroyed but no trace of old corner
which is said to be a stone. I therefore
re-establish the corner at this point
as follows,

Set a rock 24 x 14 x 10 inches
18 inches in the ground for corner to