

North between sections 1 & 6
 Va. 110° 34' E

4000 Set cedar post $4 \times 4 \times 4$ long 12'
 in ground for $\frac{1}{4}$ sec. cor marked
 $\frac{1}{4}$ S. on W. face
 Dug pits $18 \times 18 \times 12$ N & S $5\frac{1}{2}$
 distant

Raised mound of earth 2ft high
 4ft base around post
 8000 Red Cedar post $8 \times 8 \times 5$ 24" in
 ground for cor to Townships
 21 & 22 N. Ranges 50 & 51 E.
 marked J. 22 N. S. 31 on N.E.
 R. 51 E. S. 6 on S.E.

J. 21 N. S. 1 on S.W. R. 50 N. S.
 36 on W. face with 6 notches on each edge
 Dug pits $24 \times 18 \times 12$ 6ft distant
 lengthwise on each line
 Raised mound of earth $2\frac{1}{2}$ ' high
 5ft base around post
 Land level. So chs dense sage
 Soil sandy 1st rate
 No timber

April 10th 1893