

76

General Description

All of this township surveyed under this contract is mountainous and watered by several small springs & by Idaho Road Cañon Creek and Dry Susie Creek both of which run dry during the summer.

There is good grazing throughout

In some cases I could not set stones to required depths but set all such firmly in the ground down to the bedrock.