

W. bdy of T. 32 N. R. 54 E.

On November 28th having been notified of the approval of my contract No. 211 I complete the survey as follows
 N bet trees 1 + 6.

In mountains

- 500 Spur N E.
 2000 Ravine N E.
 2900 Spur N E.
 4500 Set a redwood post 3 ft long 3 ins. dia with marked stone 2 1/2 ins in the ground for 1/4 sec. over marked N & on N face, dug pit 18 x 18 x 12 ins N + S 3 ft. dist and raised mound of earth 3 1/2 ft. base 1 1/2 ft. high W. of cov.
 4800 Ravine N W.
 6000 Spur N W.
 8010 Intersect W bdy of Sp. 4 & 5 bld. E of cov to T. 32 N. R. 53 + 54 E which is a rock firmly set & properly marked & witnessed agreeing with surveyor