

Re-Survey of East bdy of T439 R62E

Inspection of the East boundary made October 24th & November 18 has demonstrated the necessity for a re-survey as will be more clearly shown in the following notes.

From the Cor to Tps 42 & 43 N. R. 63 E
North on West boundary of Sec 31.

Mountains

450. Low ridge N. E. by E

1050. Canal N. E. by E

1400. Ridge N. E. by E

2050. Quarry N. E. by E

2535. Cor to Tps 42 & 43 N. R. 62 E

2650. Ridge N. E. by E

4000 After diligent search I am unable to find any trace of old 1/4 sec. cor.

Set a limestone 14x9x4 ins 9 ins in the ground for 1/4 sec. cor marked 1/4 sec. N. face dug to 18x18x12 ins N. & S. 2 ft. dist and raised a