

- S 89° 50' ~~N~~ along S Bdy Sec 31
over gently rolling land
through Sage brush.
- 20.50 Rock creek 10 lks wide course
N.W.
- 27.80 Road bears N.W. and S.E.
- 35.30 dry drain course North.
- 36.01 The closing cor sees 5 and 6 Sp
30 N. R. 46. E. which is a stake
totally decayed. I reestablish old
cor by setting a granite stone
14x12x10 ins 10 ins in the ground
for closing cor sees 5 and 6.
Marked with 5 notches on E
and 1 notch on Wedges, C.C. on
S face. dig pits 24x18x12 ins
crosswise on each line E and W
3 ft and 2 7 ft dia - raise
a mound of earth 4 ft base
2 ft high S of cor.
- 40.21 The Sta 14 sec cor S Bdy. Sec 31.
Sp 31 N. R. 46. E. which is a stake
totally decayed I reestablish cor.
by setting a granite stone 15x10x5
ins 10 ins in the ground at exact
point of old cor. for Sta 14 sec cor
Marked 14 S.E. on N face. Dig