

Survey Subs. Sp. 35th N., R. 70 E.

Chains

40.00 N. 0° 2' E, bet. ^{Secs} 3 and 4
 Put a granite rock 12x8x4
 ins. 8 ins. in ground for 1/4 sec.
 cor. mkd. 44 on W. face; raise
 mound of rock 2 ft. base, 1 1/2
 ft. high W. of cor. Pits im-
 practicabl.

80.05 Intersect 9th Standard
 at 38.70 chs. E. of cor. to
 Secs 32 and 33, Put a lime
 stone, 18x10x6 ins, 14 ins in
 ground for closing cor. to sec.
 3 and 4, mkd. with 3 grooves
 on E. and W- and C on S,
 faces; raise mound of rock
 2 ft. base, 1 1/2 ft. high S. of cor.
 Pits impracticabl.

Naud level: 80.05 chs.
 Soil gravelly - 3rd rate.
 Grasswood
~~80.05 chs. level.~~

Nov. 1st 1907.