

Survey of Subdivisions of T. 37 N. R. 70 E.

- E. bet. secs. 4 and 9.
 4.75 wash NW.
 10.00 wash NW.
 40.00 Set a granite stone 15x8x4 ins.
 10 ins. in ground marked $\frac{1}{4}$
 on N. face for $\frac{1}{4}$ sec. cor. bet.
 secs. 4 and 9, and I raised
 a mound of stones 2 $\frac{1}{2}$ ft. base
 1 $\frac{1}{2}$ ft. high N. of cor.
 Pits impracticable
 44.00 Ravine NW.
 53.00 Wash N.
 80.00 Cedars.
 81.00 Wash N.
 94.75 Intersect state line 7.78 chs.
 S. of cor to state line marked No. 16
 Here I set a quartzite stone 15x10x8
 ins. 10 ins. in ground marked
 C.C. on W. face with 5 grooves on
 S and 1 on N. face for closing
 cor to secs. 4 and 9, and I raised
 a mound of stones, 2 $\frac{1}{2}$ ft. base,
 1 $\frac{1}{2}$ ft. high, W. of cor.
 Pits impracticable.
 Land mountainous 94.75 chs.
 Soil 2nd rate.
 Sagebrush, greasewood, cedar.