

Survey of Subdivisions of T. 37 N. R. 70 E.

Lehans N. 0° 1' E. bet. sec. 4 and 5.

6.00 Dry Channel W.

19.00 Foot of gradual slope.

40.00 Set a limestone 14 x 8 x 6 ins.
10 ins. in ground marked
 $\frac{1}{4}$ on W. face for $\frac{1}{4}$ sec. cor.
bet. sec. 4 and 5. and raised
a mound of stones 2 $\frac{1}{2}$ ft. base,
1 $\frac{1}{2}$ ft. high, W. of cor.
Pits impracticable

56.00 Ravine W.

68.00 Ridge W.

78.00 Dry channel W.

82.43 Intersect N. bdy. 4.07 chs. W. of cor.
to sec. 32 and 33. Here I set
a granite stone 16 x 12 x 8 ins.
11 ins. in ground marked
C.C. on S. face with 4 grooves on
E. and 2 on W. face for closing
corner to sec. 4 and 5 and I
raised a mound of stones
2 $\frac{1}{2}$ ft. base, 1 $\frac{1}{2}$ ft. high. S. of cor.
Pits impracticable

Land fairly level 82.45 chs.

Soil 2nd rate.

Sagebrush, greasewood, cedars.

July 22nd 1904.