

Chaus

Survey of N. bdy. of T. 14 N., R. 27 E.  
 also impossible.

We begin at a pt. 8.45 chs.  
 S.  $80^{\circ} 23'$  W. from cor. common  
 to the two Tps. 14 and 15 N.;  
 R. 26 E. which is

A quartz stone,  $7 \times 7 \times 16$  ins.  
 previously described <sup>on</sup> Aug. 5

Set a granite stone,  $20 \times 7 \times$   
 $3$  ins. 15 ins. in the ground  
 for a closing Tp. cor. for  
 Tps. 14 and 15 N., R. 27 E.  
 marked C C on E. face;  
 with 6 grooves on N, E, and  
 S faces, and raise a  
 mound of stone, 5 ft.  
 base,  $2\frac{1}{2}$  ft. high, E. of  
 cor. Pts <sup>2</sup> impracticable.

Thence we run  
 C. on a true line, bet. secs.  
 6 and 31.

Over mountainous and level  
 land; descend down steep  
 mountain side.

15.00 Base of mountain bears  
 N. and S.; thence E. over  
 a gentle slope.

35.05- Set a redwood post, 3 ft.