

Resurvey of the 5th St. Par. N. through R. 28 E.

Chain S. $89^{\circ}58'$ W on secant and S. Ldy.
of sec. 31

Over level land.

40.00 Fall 100 ft S. of $\frac{1}{4}$ sec. cor. on S.
Ldy. of sec 31. a conglomerate
rock as decided by notes of
Surveyor General. excepting
 $\frac{1}{4}$ was omitted on N. face
I cut $\frac{1}{4}$ on N. face.

Mound in good condition.

80.00 Fall 300 ft. S of the St. cor of T.
26 N., Rgs. 27 and 28 E.

A volcanic stone $10 \times 6 \times 6$ ins.
loosely set in ground, mound of
rock scattered. I destroy old cor.
and at exact point set a basalt
stone $20 \times 10 \times 10$ ins. 15 ins. in the
ground inkd. S. on N. face.
with 26 N on N, 28 E. on E. &
grooves on N.E. and W. faces.
and raise a mound of stone
4 ft. base 2 ft high N. of cor
Land level. Pto impracticable
Soil sandy 1st rate
Sage brush and scattering
bunch grass.

No timber.

July 6, 1905