

Re-survey 5th Standard North-chains

Prior to commencing the survey of the 5th Standard Parallel North through a portion of Range 56 E., I retraced as follows:-

July 29-1904, from the Standard Cor. to Secs 31 and 32, Tp. 26 N., R. 56 E, which is cedar post 2 1/2 ins. sq. 3 ft. long, set in a mound of earth, scribbled S 31 on W. face, T XXV N. RLVI E on N. face, S 32 on E. face, with S grooves on E. and 1 on W. faces; I retrace the S. bdy. of sec. 32, running E. and at

40.00 Find no trace of Standard 1/4 sec. cor.

80.00 Find no trace of Standard sec. cor. and continue my line.

120.00 Find no trace of Standard 1/4 sec. cor.

160.00 Find no trace of Standard