

4.
186

Re Survey of Fourth Std. Par. N. Through R 23 E.
Chambers. Nov. 11-1906 8 h. 0 m. a.m. 2. m. t.

Preliminary to Commencing
the subdivision of the northern
part of this T^p. I run then a
blank line on the 4th STD.
Parallel, the N. bdy. of T. 23 N.
in search of Standard $\frac{1}{4}$ sec.
and sec. cor.

- 40.30 I find a $\frac{1}{4}$ sec. cor. 17¹⁷¹ yds. S. of
line., a basal stone
14 x 8 x 6 ins. Vaguely marked
loose in ground in a scattering
mound of stone.
- 80.51 I find a stone 12 x 10^{ins} - 6 ins. out
of ground - (few stones around
it) marked with 5 grooves on W
and one groove on E. faces 49 yds. S. of
line, nothing to indicate standard
cor. - no pits and no mound.
- 120.33 I find a stone 8 x 6 x 6 ins.
43 yds. S. of line. marked with
 $\frac{1}{4}$ on N face. in a mound of
stone.
- 160.54 I find a limestone 52 yds S. of
line. - marked with 2 grooves on
E and 4 grooves on W. faces.
Stone badly cracked in a