

NORTH BOUNDARY OF T.6 S.,R.47 E.

CHAINS

6 S on S., C C 47 E on W face, with 6 grooves on N., S., and W. faces, and raise a mound of stone, 2 ft. base, 1½ ft. high, W. of cor.

Pits impracticable.

I destroy all marks on the cor. of Tps. 5 and 6 S., R. 47 E., that pertain to R. 47 E.

Land, level.

Soil, sandy, 3rd. rate.

No timber; undergrowth, greasewood and sage.

Dense undergrowth on 80.00 chs.

January 7, 1907.

BOUNDARIES OF T.6 S.,R.47 E.

Latitudes, departures and closing errors.

Line Designated	True Bearing	Distance	Latitudes		Departures	
			N.	S.	E.	W.
		Chs.	Chs.	Chs.	Chs.	Chs.
S. Bdy.	S. 89° 39' W.	477.70		2.92		477.70
W. Bdy.	North	480.00	480.00			
N. Bdy.	East	476.56			476.56	
E. Bdy.	South	474.15		474.15		
Convergency					0.55	
			480.00	477.07	477.11	477.70
			477.07			477.11
Error in lat. and dep.			2.93			0.59

GENERAL DESCRIPTION

This township is rocky and mountainous in the western, northern and southeastern portion, while the balance of the township is nearly level draining to the northeast, and generally covered with a dense growth of desert brush. There is no timber, surface water or indications of mineral found in this township.