

2.

Resurvey of sub-divisions of Tp. 42. N., R. 39E.

Chains

Land level and rolling.

Soil Loamy and stony, 1st. and 4th. rate.

No timber.

May 15, 1908.

Resurvey of 9th. St. Par. N., S. bdy. sec. 32, R. 26E.

April 20, 1908: To account for the discrepancy appearing in my connections at the closing cors. of secs. 3 and 4 and 2 and 3 on the 9th. St. Par. N., I retrace the St. Par. as follows;-

From the standard cor. of secs. 31 and 32, previously described, I run

East on a random line on S. bdy. of sec. 32.

40.00 No trace of standard $\frac{1}{4}$ sec. cor. can be found.

83.10 Standard cor. of secs. 32 and 33 bears N. 9.5 lks.

Thence I run

S. 89° 56' W. on a true line on S. bdy. sec. 32.

15.80 Road bet. Denio, Oregon and Surprise Valley, Calif. bears N.W. and S.E.

15.90 Wire fence bears N.W. and S.E. Enter level bottom land.

38.90 N. branch Thousand Creek course S.E.

39.10 Wire fence bears S. 20° W. and N. 20° E.

41.55 Set a quartz porphyry rock 18x14x5 ins., 12 ins. in the ground for standard $\frac{1}{4}$ sec. cor., mkd.

S C $\frac{1}{4}$ on N. face; and raise a mound of stone 3 ft. base, 2 ft. high N. of cor. Pits impracticable.

45.10 Leave level land, ascend rolling sand hills.

62.40 Closing cor. of secs. 3 and 4, heretofore described.

69.50 Ridge bears N.W. and S.E.

73.40 Dry run in broad flat draw, course N.

83.10 The standard cor. of secs. 31 and 32.

Land level and rolling.

Soil clayey and sandy, 1st. and 3rd. rate.

No timber. April 20, 1908.