

## Survey of Exteriors of T. 17 N., R. 43 E.

Chains	From the cor. of Tps. 16 and 17 N., R. 44 E., already described, I run N. on the W. bdy. of sec. 31.
1.54	Rock Creek canon, course SE.,
2.24	Rock Creek, 3 lks. wide, 2 ins. deep, course SE.,
13.45	Tree, the witness cor. of Tps. 16 and 17 N., R. 43 E. 20 lks. S. of true place for cor.
24.00	Ascend,
40.00	Cor. falls on rock in place, 5 ft.x4ft.x1 ft. above ground, mark X at exact point with $\frac{1}{4}$ W of X for $\frac{1}{4}$ sec. cor. referring to sec. 31, and raise a mound of stone 2 ft. base, $1\frac{1}{2}$ ft. high W. of cor. Pits impracticable.
51.15	Summit of ridge, bears E. and W.,
53.65	Set a lava stone 22x14x5 ins., 16 ins. in the ground, for $\frac{1}{4}$ sec. cor. to sec. 36, marked $\frac{1}{4}$ on W. face, and raise a mound of stone 2 ft. base, $1\frac{1}{2}$ ft. high W. of cor. Pits impracticable. From which A pine, 24 ins. diam., bears S. 5° W., 38 lks. dist., marked $\frac{1}{4}$ S 36 B T.
80.00	Set a lava stone 20x8x6 ins., 15 ins. in the ground for cor. to secs. 30 and 31, marked with 5 notches on N., and 1 notch on S. edge, and raise a mound of stone 2 ft. base, $1\frac{1}{2}$ ft. high E. of cor. Pits impracticable. Land, mountainous. Soil, loose rock, third rate. Timber, pine, cedar, mahogany and sagebrush. Mountainous land, covered with timber, very difficult to survey, 80.00 chs.