

Resurvey of the 7 Th. Standard Parallel N.

through Range 67 E.

(5) (2)

chains

From the above cor. I run

West along the S.bdy.sec.33

40.00

After diligent search I fail to find $\frac{1}{4}$ cor.

80.20

Pass 24 lks.N.of the cor.of secs.32 and 33.

From the above cor.I run

West along the S.bdy.sec.32

40.00

After diligent search fail to find $\frac{1}{4}$ sec.cor.

80:45

Pass 4:22 chs.S.of the standard cor of secs.31 and 32

April 1. -1909

April 2:

From the above cor. I run

West along the S.bdy.of sec.31

40.00

After diligent search fail to find the $\frac{1}{4}$ sec.cor.

79.94

Pass 5.12 chs.S.of the standard cor.of Tps. 36 N.Rs.
67 and 68 E.

Retracement of the 7th. Standard Parallel through
a portion of Range 67 E.

From the standard cor. of tps.36 N.Rs.67 and 68 E.

I run West

37.56

Pass 1.94 chs. S.of the C.C.of Tps.35 N.Rs.67 and 68 E.

The above mentioned cor.being a post in bad state of
preservation, I destroy it and reestablish cor.at the same
point as follows:

Set granite stone 22x8x4 ins.,17 ins.in the ground,
for closing cor.of Tps.35 N.Rs.67 and 68 E.,marked C C on
S.with 6 grooves on S.E.and W.faces, dig pits 30x24x12 ins
crosswise on each line E.and W.,4 ft.,and S.of stone 8 ft.
dist.,and raise a mound of earth 5 ft.base,2 $\frac{1}{2}$ ft.high S.
of cor.

April 2 1909.

April 3:

From the above described cor. I run

S.87°3'E.along the S.bdy.sec.36

Across level land

37.61

Intersect the standard cor. of Tps.36 N.Rs.67 and 68