

Subdivisions of T. 34. N.R.69 E.

(3)

chains

- 77.63 Intersect the W. line of the Tp. at the cor. of secs. 1-6-7 and 12. A stone previously described.
Thence \perp run
East on a true line bet. secs. 6 and 7
Across level land
- 6.50 Road bears N. 30°W. and S.30°E.
- 10.00 Dry wash, course N. 45° E.
- 19.00 Dry wash, course N. 45°E.
- 34.50 Road, bears S. 45° E. and N. 45° W.
- 37.63 Set a lime stone 20x8x4 ins., 15 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on the N. face, dig pits 18x18x12 ins., E. and W. of stone, 3 ft. dist., raise a mound of earth, 3 $\frac{1}{2}$ ft. base, 1 $\frac{1}{2}$ ft. high, N. of cor.
- 38.50 Telephone line, bears N. 39°W. and S.39°E.
- 77.63 The cor. of secs. 5-6-7 and 8.
Land level
Soil gravelly, 3rd. rate.
Thin growth of sage brush.

May 25 . 1909

*Boundaries of T. 34 N. R. 69 E.
Latitudes, departures and closing errors.*

Line Designated	True Bearings	Distance Chs.	Latitudes		Departures	
			N. Chs.	S. Chs.	E. Chs.	W. Chs.
S. line Secs. 5 and 6	West	157.65				157.65
W. line Sec. 6	North	80.00	80.00			
N. line Secs. 5 and 6	East	157.51			157.51	
E. line Sec. 5	S 0° 3' E.	8000		8000	.07	
Convergencies	—	—			.04	
Totals			80.00	80.00	157.62	157.65
Errors in			Lat 00	00	Dep	157.62 .03

General Description.

The land of this township is level, with a sandy soil supporting a scant growth of sage brush. There is no water within the surveyed portion and are there no settlers.