

Resurvey of the E. Bdy. of Tp. 35 N. R. 67 E. (1)

Chains April 22-1909: I found the original cor. set for cor. of Tps. 34 and 35 N. Rs. 67 and 68 E.

This cor. being in a bad state of preservation I destroyed it and replaced it with a new cor. in the same position as follows:-

Set a limestone 22x10x6 ins., 16 ins. in the ground for cor. of Tps. 34 and 35 N. R. 67 E. M. D. B. and M., only, (as the special instructions issued to me under the current contract require that a new Closing Township corner for cor. of Tps. 34 and 35 N. R. 68 E. shall be set); marked 34 N on SW., 67 W on NW., with 6 notches on N. and W. edges, and raised a mound of stone 3 ft. base, 2 ft. high W. of cor. Pits impracticable.

October 24-1910.

From the above described Tp. cor., I ran

N. 1° 1' E., on the E. line sec. 36

Through scattering pine and cedar timber, ascending mountainous land

18.50 Spur bears N. 45° E. and S. 45° W. descend

29.00 Gulch course West, ascend

38.00 Spur bears E. and W. descend

40.16 The $\frac{1}{4}$ sec. cor. established by me April 22-1909, as follows:-

Set a limestone 18x10x6 ins. 12 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on the W. face. whence

A pine tree 24 ins. in diam. bears West 9 lks. dist.

marked $\frac{1}{4}$ S 36 B T. No other trees being available I raised mound of stone 3 ft. base, 2 ft. high W. of cor. Pits impracticable (cable

56.00 Gulch course W., ascend

66.00 Summit of main spur of mountain bears E. and W. descend

80.32 The cor. of secs. 25 and 36, set by me April 22-1909, as follows:-

Set a limestone 20x8x6 ins. 15 ins. in the ground for cor. of secs. 25 and 36, marked with 5 notches on N. and 1 notch on S. edge, from which

A pine tree 5 ins. in diam., bears N. 3° W. 40 lks. dist.

marked T 35 N R 67 E S 25 B T