

Retracement of Part of the Seventh Standard Parallel South,
through Range 65 East.

Chains Preliminary to commencing the subdivision of
this township, T²⁸S

East on the S. bdy. of Sec. 36, T. 28 S., R. 65 E., on
the Seventh Standard Parallel South

40.00 Intersect the Standard $\frac{1}{4}$ sec. cor., which is a
granite stone 5x10x9 ins. above ground, marked
and witnessed as described by the Surveyor
General.

59.53 Intersect the closing cor. of T. 29 S., Rgs. 65 and 66
E., which is a pine post almost entirely decayed,
and the marks are nearly obliterated. I destroy
all traces of the old corner and reestablish it at
the same point, as follows:
Set a quartzite stone, 16x10x5 ins., 11 ins. in the
ground, for closing cor. of T. 29 S., Rgs. 65 and 66
E., marked
L & L on S., with 6 grooves on S., E. and W.
faces; and raise a mound of stone, 2
ft. base, 1 $\frac{1}{2}$ ft. high, S. of cor.

80.00 No corner could be found after diligent search.
Set an iron post 3 ft. long, 3 ins. diam., 24 ins.
in the ground for Standard corner of T. 28 S.,
Rgs. 65 and 66 E., with brass cap marked

T 28 S	
R 65 E	R 66 E
S 36	S 31
1911	

and raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$ ft.
high, N. of cor.

May 1, 1911