

Resurvey of the W. bdy. of T 19 N, R 22 E,
west of secs. 7, 18, 19, 30 and 31

chains.

on N. and 2 notches on S. edge, set
in a mound of stone

I continue my blank line south,
and at 39.65 chs. find the $\frac{1}{4}$ sec. cor.
falling 2.07 chs W. of my line.

This cor. is a basalt stone 11×6 ins.
by 10 ins. above ground, firmly set
in the ground, marked $\frac{1}{4}$ on the
W. face, and properly witnessed by a
mound of stone 2 ft. base, $1\frac{1}{2}$ ft.
high W. of cor.

At 79.60 chs. I find the cor. of secs.
25, 30, 31 and 36, falling 2.29 chs W. of
my line. This cor. is a basalt stone
 $18 \times 10 \times 6$ ins, marked with 5 notches
on N. and 1 notch on S. edge and
set in a mound of stone.

I continue my blank line south
and at 35.36 chs. find the $\frac{1}{4}$ sec. cor.
falling 2.11 chs W. of my line.
This cor. is a basalt stone, $16 \times 9 \times 6$
ins. marked $\frac{1}{4}$ and lying on the
ground in an old pile of stone.

At 75.78 chs. I find the cor. of T 19 N
Rs. 21 and 22 E, falling 2.37 chs W. of my
line. This cor. is on the N. bdy. of
T 18 N, R 21 E at S 89° 34' W, 39.17 chs.
from the N.E. cor. It is a basalt
stone $17 \times 9 \times 5$ ins. marked with
6 notches on each of the N, E, and W.
edges and set in a mound of stone.

Since the greater part of this line
is out of limits in either or both
distance or course, and a number
of the corners are in poor con-
dition it will be necessary to re-
survey it. I therefore return to
the cor. of secs. 1, 6, 7 and 12
and re-survey as follows: