

Subdivision of T.39 N., R.18 E.


Chains.

238.15 Intersect 46th mile post, which is a cedar post, 6x6 ins. square, 5ft. above ground, marked on the North side 0 46 miles. on the West side Cal., on the East side Nev., and on the South side 1872 L 120.

thence I run.

N. 0° 4' E., on the West bdy of Sec. 5.

240.00 Set an iron post, 3ft. long, 2 ins. diam., 24 ins. in the ground, for 3 mile cor. with brass cap mkd:



275.63 Intersect the closing cor. of T.39 and 40 N. R.18 E.

(here to fore described.

Land, mountainous.

Soil, rocky. 4th rate.

No timber.

Drainage W.

August 25 1911.

General Description.

This township is rough and mountainous. in the Northern and Eastern part, rolling in the interior. and nearly level in the Western. parts. while level meadow land, is found, in the SW. part. The township is very dry except for a few small streams. Small groves of Quaking asp and junipers. are found in the interior. the soil in general. stony, and can nearly all be classed as, 4th rate.

James D. Archer,  
U.S. Transitman.