

Re-survey of 1st. Standard Parallel
North, through R 59 E.

183⁵

chains.

and re-survey it as follows:

From the Standard corner of T 6 N,
Rgs. 59 and 60 E.

I run

N 89° 49' W, south of sec. 36.

I measure the distances twice
with the same set of chainmen,
taking the mean of the two
measurements.

Descend over stony north west
slope.

30.00 Wash, course N. E.

Leave stony, sloping land, and
enter level land.

40.00 At this point, where the old
standard $\frac{1}{4}$ sec. cor. stood.

Set an iron post 3 ft. long,
1 in. diameter, 24 ins. in the
ground for standard $\frac{1}{4}$ sec.
cor. with brass cap mkd.

S 36 $\frac{1}{4}$
SC

1913

dig pits 18 x 18 x 12 ins. E. and W.
of post 3 ft. dist. and raise
a mound of earth 3 $\frac{1}{2}$ ft.
base, 1 $\frac{1}{2}$ ft. high N. of cor.

80.00 Set an iron post 3 ft. long,
3 ins. diam. 24 ins. in the
ground for standard corner of
secs. 35 and 36, with brass
cap mkd.

T 6 N R 59 E
S 35 | S 36
SC

1913

dig pits 24 x 18 x 12 ins.; crosswise