

Resurvey of N. Bdy of S. 6, T27N, R36E

chains ^{Surveyed by Thos. A. Steigh.}
X From the cor. of Tps. 27 and 28
N, Rs 35 and 36 E.

Retrace along the N. bdy of Sec. 6.
East.

Over dry lake bed.

41.97 Fall 5.03 chs. S. of old decayed
post, marked for $\frac{1}{4}$ cor. of secs.
6 and 31.

As this cor. is so far out of
limits, both in distance,
and bearing and no sub-
division depending on this
line I destroy all traces of
old cor. and at

40.00 Set an iron post, 3 ft. long,
1 in. in diam., 24 ins. in
the ground, for $\frac{1}{4}$ sec cor.,
with a brass cap marked,

531
 $\frac{1}{4}$
56
1913

dig pits, 18x18x12 ins.; E. and
W. of cor. 3 ft. dist; and raise
a mound of earth, 3 $\frac{1}{2}$ ft base,
1 $\frac{1}{2}$ ft. high. $\frac{1}{4}$ of cor.

80.00 Set temp cor.

87.19 Fall 11.90 chs. S. of old decayed
post. I destroy all traces of old
cor. and at the temp. point.
Set iron post 3 ft. long, 3
ins. in diam., 24 ins. in
the ground, for cor. of secs.
5, 6, 31 and 32., with brass
Cap. marked,

T28N
531 | R36E
5.6 | 5.32
T27N | 55
1913