

Dependent Resurvey of the California-Nevada State Line

9.

Chains

- 4 ft. deep, on level land, and a light sandy clay loam, dry medium texture very rocky is found on rolling and mountainous land. Undergrowth, sagebrush, willows, shadscale and greasewood. No timber.
- This cor. is 260 ft. above level land.

---

- S. 0° 37' E., on 97 Mile.
- Over rough rugged rocky broken mountainous land, asc. along a broken E. slope, covered with sliderock and many volcanic outcrops.
- 4.90 Wire fence, bears E. and W.
- 8.90 Top of ascent, 50 ft. above cor., bears NW. and S. 20° E.; thence over nearly level bench.
- 16.50 Desc. over small rimrock, bears NE. and SW. 135 ft. to
- 31.80 Gulch, course E.; asc.
- 34.20 Wire fence, bears E. and W.
- 80.28 Intersect the 97 mile cor., which is a lava stone, 18x16 x10 ins., on top of a large mound of stone, mkd. and witnessed as described by the surveyor general. I rebuild this cor. at its original position.
- This cor. is 360 ft. above gulch.
- Land, rough mountainous. Soil, light, sandy clay loam, medium texture, dry; much sliderock of lava formation. Undergrowth, sagebrush, shadscale and greasewood. No timber.

---

- S. 1° 05' E., on the 98 Mile.
- Over rough broken mountainous land, asc. along NE. slope, through undergrowth and surface covered with lava rock.
- 2.00 Top of rimrock of table land, 55 ft. above cor., bears N. 20° W. and S. 70° E. thence over nearly level table land.
- 30.00 Edge of rimrock of table land, bears N. 30° W. and S. 30° E., desc.
- 49.80 Ravine, 110 ft. below rimrock, course SE.; asc.