

Dependent

Resurvey of a portion of the California-Nevada State Boundary Line

11

Chains

at its original position as follows:

Set an iron post, 3 ft. long, 3 ins. diam., 24 ins. in the ground, for mile cor. 59, with brass cap mkd.

CAL	NEV
59	M
1918	

and raise a mound of stone, 5 ft. base, 3 ft. high around the cor.

Land, level and rolling. Soil, light sandy clay loam, medium texture. Undergrowth, sagebrush and buckbrush
Timber, Poplar.

S. 0° 03' E., on a true line, on the 60th Mile.

Over rolling land, through dense undergrowth asc. 25 ft. to

- 7.00 Point of spur, projects N. 20° E.; desc. 12 lks. to
- 10.90 Spring branch, 3 lks. wide, 1 ins. deep, course NE.; asc.
- 16.67 Intersect E. and W. line, bet. secs. 23 and 26, at a point, 2 lks. W. of the cor. of secs. 23, 24, 25 and 26, which is a sand stone, 14x12x8 ins. firmly set in a mound of stone, mkd. and witnessed as described by the surveyor general.
- 27.00 Gulch, course NW.; asc.
- 56.33 Fall 4 lks. W. of the old $\frac{1}{4}$ sec. cor., bet. secs. 25 and 26, which is a sand stone, 26x14x5 ins. firmly set in a mound of stone, properly mkd.
- 74.18 Intersect the reestablished closing cor. of Tps. 37 and 38 N., R. 18 E., which is an iron post, 18 ins. above the ground, 3 ins. diam., mkd. and witnessed as described by the surveyor general.
- 79.44 Intersect the 60th Mile cor. which is a cedar post, 3 ft. long, 4 ins. sq. mkd. and witnessed as described by the surveyor general. This mile cor. is 650 ft. above spring branch.

Land, rough mountainous. Soil, light shallow clay sandy loam, medium texture, dry and very rocky. Undergrowth, sagebrush, buckbrush and a fair growth of grass. Timber scrub juniper.