

Boundaries of T. 22 N., R. 66 E.

Latitudes, departures, and closing errors.

Line designated	True bearing	Distance	Latitudes		Departures	
			N.	S.	E.	W.
S. bdy. T. 22 N., R. 66 E.	N. 89° 54' W	479.60	.84			479.60
W. bdy. T. 22 N., R. 66 E.	North.	480.00	480.00			
N. bdy. T. 22 N., R. 66 E.	S. 89° 55' E	478.78		.72	478.78	
E. bdy. T. 22 N., R. 66 E.	South.	480.00		480.00		
Convergency					60	
Totals			480.84	480.72	479.38	479.60
			480.72			479.38
Error in lat.			.12	Error in dep.		.22

General Description.

The surface in the east part and in the south central part of this township, is rough mountainous, parts of it being so rough and rugged as to be practically inaccessible. The remainder of the surface is heavily rolling and broken. Long, low ridges and spurs extend between the washes and draws, and the surface of the land is so rough and broken as to render it unfit for cultivation even if there was enough moisture. The soil is generally very rocky and dry, containing little or no loam, except near the springs shown, and along Siegel creek, and in Spring Valley. Spring Valley extends in a southerly direction across the township and ranges in width from 10 to 30 chs. The soil is a deep rich loam, but in places contains some alkali. Spring Valley is well watered. Most of the mountain slopes are covered with a dense growth of pinion pine, juniper, and mountain mahogany timber. Over the most