

Subdivision of T. 23 N., R. 66 E.

Chains.

76.00 Dry wash, 15 lks. wide, 3 ft. deep,
course S. 20° W.

79.98 The cor. of secs. 5, 6, 7 and 8.

Land, rolling and level.

Soil; a mixture of clay, sand and gravel;
good depth; medium texture; 1st.
rate.

No timber.

Undergrowth, sagebrush and grease-
wood.

July 15, 1913.

Boundaries of T. 23 N., R. 66 E.

Latitudes, departures, and closing errors.

Line designated	True bearing	Distance	Latitudes		Departures	
			N.	S.	E.	W.
S. bdy. T. 23 N., R. 66 E.	S. 89° 55' E.	478.78		.70	478.78	
E. bdy. T. 23 N., R. 66 E.	N 01° 11'	480.00	480.00			
N. bdy. T. 23 N., R. 66 E.	N. 89° 54' W.	478.26	.84			478.26
W. bdy. T. 23 N., R. 66 E.	South.	480.00		480.00		
Convergency						.60
Totals			480.84	480.70	478.78	478.86
			480.70			478.78
Error in lat. - - -			.14	Error in dep.		.08

General Description.

The surface in the east half of this township is mainly mountainous. The west half is very heavily rolling and broken, except in Spring Valley, which is flat. Spring Valley extends in a southerly direction entirely across the township, in the west portion of same, and varies in width from 20 to 40 chs. The soil in the mountainous portion of the township,