Resurvey of the west bdy. of T. 28 N. R. 39 E.

Chains.	/	9		
		T28N		
		R38E	R39E	
		SI	S65	
	7	S12	S7	
		1914		

dig pits 18 x 18 x 12 ins. in each sec.,  $5\frac{1}{2}$  ft. dist.; and raise mound of earth 4 ft. base, 2 ft. high, W. of cor.

Land nearly level, slopes and drains west.

Soil, gravely clay loam, 24 ins. deep.

Subsoil, gravel.

No timber.

Undergrowth, sage brush, shad scale and bunch grass.

Land suitable for farming or grazing.

Oct. 12, 1914. Perfert.

Oct. 30, 1914.

N. 0° 27' W. on true line bet. secs. 1 and 6.

Over nearly level land, through sage brush and shad scale.

1.80 Wash, 8 lks. wide, 1½ ft. deep, course S. 70° W.

18.20 Wash, 10 lks. wide, 2 ft. deep, course S. 85° W.

40.06 Proportionate measurement, set an iron post 3 ft. long,

1 in. in dia. 26 ins. in the ground for the re-established \$\frac{1}{4}\$ sec. cor. of secs. 1 and 6, with brass cap mkd.

and raise mound of stone 2 ft. base, 12 ft. high, west of cor.

44.70 Wash, 6 lks. wide, 1 ft. deep, course N. 80° W.

48.30 Creek of running water, 6 lks. wide, 2 ins. deep, course west.

69.70 Wash, 20 lks. wide, 10 ins. deep, course N. 80° W.

Previously described. Set an iron post 3 ft. long, 3 ins. in dia. 24 ins. in the ground by the side of the old cor., for the re-established cor. of Tps. 28 and 29 N.

Rs. 38 and 39 E., with brass cap marked