

## Resurvey of the W. Bdy. of T. 35 N., R. 46 E.

7.

Chains

and raise a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high,  
W. of cor.

- 42.00 Ravine, course NW., 35 ft. below  $\frac{1}{4}$  sec. cor.  
43.00 Low ridge, bears E. and W., 40 ft. above wash.  
44.15 Wash, course SW.  
50.00 Spur of hill, slopes SW., 90 ft. above wash.  
53.85 Wash, course W. Ascend steep rocky S. slope.  
79.54 (Proportional distance) 355 ft. above wash.  
On W. slope of mountain spur.

Set an iron post 3 ft. long, 3 ins. in diam., 24 ins.  
in the ground for cor. of secs. 1 and 12, with brass  
cap mkd:

T 35 N	
R45E	R46E
S 1	
S12	
1914	

and raised a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high,  
W. of cor.

Land, rough and rolling volcanic mountains, with a  
general slope to the W.  
Soil, poor quality, rocky and gravelly. Quite dry and  
shallow. Coarse texture, 4th rate.  
Fair growth sagebrush, not much grass, no timber.

N.  $0^{\circ}5'$  W. bet. secs. 1 and 6.

- 20.00 Along W. slope of high, rocky volcanic mountain.  
Shoulder of mountain.  
Descend N.W. slope.  
37.65 Ravine, course NW., 195 ft. above shoulder of mountain.  
39.77 (Proportional distance)  
Set an iron post 3 ft. long, 1 in. in diam., 24 ins.  
in the ground for  $\frac{1}{4}$  sec. cor. for secs. 1 and 6, with  
brass cap mkd:

S1 $\frac{1}{4}$		S6
1914		

and raise a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high,  
W. of cor.

- 68.10 Mountain spur, slopes W. 170 ft. above ravine.  
Descend NW. slope.  
75.65 Old road, bears NE. and SW.  
80.22 The closing corner of Tps. 35 N., Rs. 45 and 46 E.,  
120 ft. below mountain spur.

I destroy all traces of this corner and its accessories  
and reestablish it at the same point as follows:

Set an iron post 3 ft. long, 3 ins. in diam., 24 ins.  
in the ground for closing corner of Tps. 35 N., Rgs. 45  
and 46 E., with brass cap mkd:

T 36 N		
R45E	R46E	
S36		S31
CC		S6
S1		S6
R45E		R46E
1914		

and raise a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high,  
S. of cor.

Land rough and rolling, volcanic mountains, with a  
general slope to the NW.  
Soil, poor quality, rocky and gravelly, quite dry and  
shallow. Underlaid with a firm, rocky subsoil, 4th  
rate.

Fair growth sagebrush, not much grass, no timber.

Aug. 18, 1914.