


67-A

At a point $2.73\frac{1}{2}$ chs. S. $0^{\circ}22'E$. from the $\frac{1}{4}$ cor. of sec. 8, at mid point on W. side of Sec. 9, set an iron post 3 ft. long, 1 in. in diam., 26 ins. in the ground for the $\frac{3}{4}$ sec. cor. for sec. 9, only, marked on brass cap:



dig pits 18x18x12 ins. N. and S. of cor. 3 ft. dist., and raise a mound of stone 3 ft. base, $1\frac{1}{2}$ ft. high, E. of cor.

The $\frac{1}{4}$ sec. cor. for sec. 9 set by Surveyor Pray was destroyed.

BOUNDARIES OF T. 32 N., R. 49 E.

Latitudes, Departures and Closing Errors.

Line Designated	True Bearing	Dist.	Latitudes		Departures	
			N.	S.	E.	W.
N.Bdy. Sec. 2	N. $89^{\circ}52'W$.	39.86	.09			39.86
2	N. $89^{\circ}51'W$.	39.38	.10			39.38
3	N. $89^{\circ}57'W$.	39.73	.03			39.73
3	S. $89^{\circ}55'W$.	39.63		.05		39.63
4	N. $89^{\circ}39'W$.	39.65	.24			39.65
4	West	39.97				39.97
E.Bdy. sec. 5	S. $10^{\circ}W$.	32.04		31.55		5.56
5	S. $0^{\circ}10'E$.	39.43		39.43	.11	
8	S. $0^{\circ}25'E$.	39.78		39.78	.29	
8	S. $0^{\circ}22'W$.	39.37		39.37		.25
17&20	S. $1^{\circ}5'E$.	160.08		160.05	3.03	
S.Bdy. sec. 21	S. $89^{\circ}E$.	80.65		1.41	80.64	
22	S. $89^{\circ}51'E$.	39.67		.10	39.67	
22	S. $89^{\circ}30'E$.	40.70		.35	40.70	
W.Bdy. sec. 14&23	N. $0^{\circ}4'W$.	156.36	156.36			.14
11	S. $88^{\circ}48'E$.	80.24		1.68	80.22	
12	N. $0^{\circ}4'W$.	78.18	78.18			.09
1	N. $0^{\circ}13'W$.	78.48	78.48			.30
Convergency						.17
Totals			313.48	313.77	244.66	244.73
				313.48		244.66
Error in lat.				.29	Er. in Dep.	.07

GENERAL DESCRIPTION.

This fractional township in general is a low mountainous country, of rolling hills, but the greater part of secs. 16 and 21, the western part of secs. 4 and 9, and the greater part of secs. 2 and 11 are comparatively level.