99.25

dig pits, 18x18x12 ins. N. and S. of cor., 3 ft. dist. Intersect the old cor. of Tps. 36 and 37 N., Rs. 18 and 19 E., which is a cottonwood post, $1\frac{1}{2}$ ins. sq., $2\frac{1}{2}$ ft. above ground, loosely set, mkd. as described by the surveyor general. Evident remains of pits and a mound of earth. This cor. being identical with cor. No. 1 of Tract No. 48, I reestablish this cor. in its original position as follows:

Set an iron post, 3 ft. long, 3 ins. diam., 24 ins. in the ground, for cor. of Tps. 36 N. and 37 N., Rs. 18 and 19 E., and cor. No. 1 of Tract No. 48, with brass cap mkd.

dig pits, 24x24x12 ins., on lines N.E. and W. 4 ft., and S. of cor., 8 ft. dist.

Land, level. Soil, dark rich sandy loam, medium texture, clay and adobe subsoil. Undergrowth, sagebrush, greasewood, shadscale and some rye grass. No timber.

Dependent Resurvey of a portion of S. Bdy. of T. 37 N., R. 18 E.

From the reestablished cor. of Tps. 36 and 37 N., Rs. 18 and 19 E., Identical with cor. No. 1 of Tract No. 48, heretofore described.

N. 89° 19' W., on a true line, on the S. Bdy. of sec. 36, Over level land, through dense undergrowth. Along wire fence, bears N. of line 25 lks. dist. Also along road. bears N. 10 lks. dist.

36.62 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for # cor. of sec. 1, with brass cap mkd.

> 불 S 1 1919