

95a

Independant Resurvey of the E. bdy. of T. 39 $\frac{1}{2}$ N., R. 21 E.

Chains

Good growth of sage and bunch grass.

No timber.


North on true line on Independant Resurvey of the E. bdy. of T. 39 $\frac{1}{2}$ N., R. 21 E., bet. secs. 19 and 24.

Over broken land. Desc. gradual N. slope.

10.40 Stream of clear water, 3 lks. wide, 6 ins. deep, 40 ft. below sec. cor., course N. 20° W.; spring of same bears E., 50 lks. dist. Over nearly level land.

27.50 Bottom of draw, course NW.; asc. gradual SW. slope 30 ft.

37.30 Set an iron post, 3 ft. long, 3 ins. dia., 24 ins. in the ground, for cor. of Ts. 39 $\frac{1}{2}$ and 40 N., Rs. 21 and 22 E. with brass cap mkd.;



and raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high, S. of cor.

Land, rolling mountainous, general drainage NW.

Soil, rocky heavy clay and adobe loam, very shallow and covered with loose lava rocks. Soil along springs and drains leading from springs is deep loose dark loam, alluvial.

Scant growth of sage and bunch grass. Meadow grass around springs.

No timber.

Survey of the North Bdy. of T. 39 $\frac{1}{2}$ N., R. 21 E.

From the NE. cor of T. 39 $\frac{1}{2}$ N., R. 20 E., which is an anon post, 3 ft. long, 3 ins. dia., showing 12 ins. above ground, marked and witnessed as described by the surveyor general. I change the markings on the