

Survey of the Subdivisions of T. 39 $\frac{1}{2}$ N., R. 21 E.

Chains

North on random line bet. secs. 23 and 24.

37.31 Intersect the N. bdy. at a point 3 lks. W. of the cor. of secs. 23, 24, 35 and 36.

Thence,

S. 0° 02' W. on true line bet. secs. 23 and 24.

Over nearly level land. Desc. SW. slope.

24.80 Ravine and middle of small meadow, course N. 20° W., 40 ft. below sec. cor.

37.31 The cor. of secs. 23, 24, 25 and 26.


Land, gently rolling, general drainage NW.

Soil, rocky gravelly heavy clay loam, good depth, rocky subsoil.

Scant growth of sage and bunch grass.

No timber.


From the cor. of secs. 22, 23, 34 and 35, which is an iron post, 3 ft. long, 3 ins. dia., showing 12 ins. above ground; marked and witnessed as described by the surveyor general. I change the marking on the brass cap to read as follows:



N. 0° 02' W. on true line bet. secs. 34 and 35.

Over rolling land. Desc. NE. slopes.

40.00 Set an iron post, 3 ft. long, 1 in. dia., 14 ins. in the ground to solid rock, with mound of stone around, for $\frac{1}{4}$ sec. cor., with brass cap mkd.;



and raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high, W. of cor.